



June 2009

## 1997/02 Ford Expedition, 1999 Lincoln Navigator

Part #:	ACDelco # 22330M 88908259 OEM # F85Z 8286 EA
Symptoms:	Unable to disconnect lower radiator hose from the radiator.
Probable Cause of Failure:	Failure to bend the tab back on the hose to release it from the radiator.
Corrective Action:	When removing the lower hose from the radiator a screw driver must be inserted bending the tab back on the hose allowing it to disconnect from radiator.

